

D	Title	Location(exact)	Rating(current)
7215	Incomplete Interventional Radiology Pathway documents	Radiology	3
7016	Inadequate access to Interventional radiology for cancer patients, resulting in delayed diagnosis/treatment and poor experience	Radiology	4
7588	HEI CT scanner MET contact via mobile telephone	Radiology	6
7680	MRI 2 water pressure	Radiology	6
7288	Risk of damage to DR detectors Radiology is currently not able to meet the anticipated future CT/MRI demand	Radiology	6
7770	Risk of damage to DR detectors Risk of lost or delayed HEI/CT requests as a result of existing paper based process	Radiology	6
7771	Sectra PACS running slowly	Radiology	6
7808	Unregistered staff requesting ionising radiation imaging tests	Radiology	6
7837	Spinal XRay room 2 beyond end of life	Radiology	6
7915	Shortage of MKS Sonographs	Radiology	6
7854	Reliance on UHS IT infrastructure to outsource scans to Axon Diagnostics	Radiology	8
7876	IRI 7 non compliance	Radiology	8
7838	CI - recurrent failure	Radiology	8
7804	Medical Physics provision in Radiology	Radiology	8
7816	Insufficient Radiology Admin Workforce	Radiology	8

729 Weekend MRI inpatient scanning	Radiology	8
757 Referrer error wrong patient Radiation incidents	Radiology	8
7513 No MRI Safety expert in post at SDH	Radiology	8

